TOP STOUT

OUT55857

T O P S E C R E T 282235Z	1965 MAY 28	22	50 Z	
4651				
REF 3017				
1. CAMERA B 119 WAS USED ON MISSION	1-65 FLOW	N ON	17	
FEBRUARY 1965. PROCESSING WAS ACCOMPLISHED BY			1 JUN 19	365 2
2. ORIGINAL NEGATIVE:			COPIES RECEIVED_	7
2. ORIGINAL REGALIVES			Cy No. 3 Office	Act.
A. THE EXPOSURE WAS ADEQUATE AND THE RESC	DLUTION IS	FAIR	TO File	
			OS OS	
GOOD.			ADMIN SEC BR	
D on cine. Tuebe to a cine maio newstra	VITNE	. EDC	L	
B. 9R SIDE: THERE IS A FINE PLUS DENSITY	I LINE 1.0	IPK	CSD	
PARALLEL TO THE INBOARD EDGE. MINOR PROCESSING	S ANOMALTE	S TNO	1 LIDE IPD	
. HUMBER 10 THE THEORIGE EDGE HILLON I HOOFDOIN	A HIMININE	- 111	PU	
BLISTERS IN FRAMES 906 AND 1053, AN EMULSION L	IFT IN FRA	ME 16	PSD PSD-ICB	
			TID	
AND PINHOLES IN FRAMES 1856, 1862 AND 2088. A	SMALL REP	AIRE	LAR PID	
			र प्राप्तिको अस्ति क	
IS PRESENT IN FRAME 2394. A BROWN STAIN, APPRO	DXIMATELY	7.2	PAG	
THE DIAMPTER HUIGH ARREADS TO DE ASSOCIATER HIS	PU TUE VEAT	r cr	DIAXX-4	
IN DIAMETER, WHICH APPEARS TO BE ASSOCIATED WIT	in the nea	ı opl	NSA-LO	
EQUIPMENT, IS PRESENT IN THE DATA CHAMBER AREA	OF THE ED	AME A		
ENGITHERIS TO LEGERI IN THE DRIN CHANDER WERE	or the rki	THE P	100	
TO THE TAIL IDENT IN EDAMES (EDS. 1700 1006 A)	ID OZOA '	LIEDI	ABE	

C. 9L SIDE: INBOARD EDGE FOG AND STATIC OCCURS INTERMITTENTLY THROUGHOUT THE MISSION. ROLLER CHATTER IS PRESENT INTERMITTENTLY ALONG THE INBOARD EDGE. THERE ARE MINUS DENSITY STREAKS WITHIN 1.0° AND APPROXIMATELY PARALLEL TO THE INBOARD EDGE ON FRAMES 2529, 2531, 2532 AND 2533. WAVERING PLUS DENSITY STREAKS OCCUR NEAR THE INBOARD EDGE ON FRAMES 1517, 1586, 1587, 1588 AND 1619. PINHOLES AND BLISTERS ARE PRESENT INTERMITTENTLY THROUGHOUT THE MISSION.

6-90P 1

The from automotion

Formereding and

The control line

25X1

10P SECRET

HEAT SPLICES BETWEEN FRAMES 937/938 AND 1035/1036.

A PLUS DENSITY COMET SHAPED AREA IS PRESENT ON FRAME 103. THERE IS A MANUFACTURING SPLICE ON FRAME 103.

- D. BOTH SIDES: THERE IS EVIDENCE THE TITLING WAS REMOVED AND THE NEGATIVES RE-TITLED. FIVE CHANGES IN MODE OF OPERATION OCCURRED IN THE MISSION. AT THE EXECUTION OF A MODE CHANGE AT FRAME 1013 THERE IS CONSIDERABLE IMAGE SMEARING. AT THE EXECUTION OF A MODE CHANGE AT FRAME 2497 THERE ARE 3 CONSECUTIVE EXPOSURES IN THE 1L POSITION. THE MATERIAL IS TITLED TOP SECRET CHESS AND THE DATE OF THE PHOTOGRAPHY IS NOT INCLUDED IN THE TITLING. THE FRAMES ARE NUMBERED CONSECUTIVELY FROM 1 TO 2534.
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS AND THE PROCESSING COMPARES FAVORABLY WITH SIMILAR MATERIAL EVALUATED BY

3. POSITIVE:

- A. THE PI SUITABILITY IS FROM FAIR TO GOOD.
- B. THE PRINTING AND PROCESSING WAS GOOD. THE POSITIVES WERE PRINTED BEFORE THE ORIGINAL NEGATIVES WERE TITLED.
- C. CLOUDS OBSCURED APPROXIMATELY 30 PERCENT OF THE MISSION.
 TOPSECRET

/END OF MESSAGE/

